


# MAIMIN MINI-SHERE PARTS LIST



Part No.	Description	Part No.	Description	Part No.	Description
10218	Power Supply Cable	10372	Spring	10438	Disc
10250	Motor Bearing, Front	10373	Stone Screw	10440	Hex Key M2 (for 10423)
10251	Motor Bearing, Back	10374	Shaft Screw	10441	Hex Key M3 (for 10304 & 10644)
10252	Armature, 110 v.	10375	Cap	10442	Oil
10255	Armature, 220 v.	10376	Sharpening Stone	10443	Grease
10301	Retaining Ring	10380	Front Oiler	10444	Screw M2.6 x 3D Cheese Hd.
10302	Washer	10381	Front Felt	10644	Screw M4 x 10 Cap
10303	Undulated Washer	10382	Spring	30312	Hexagonal Knife
10304	Screw M 4 x 8 Cap	10383	Shoulder Screw	<b>STRETCH MINISHERE</b>	
10306	Gear Case	10384	Front Oiler Assembly	10328	Motor Adaptor Flange
10310	Gear Assembly	10390	Rear Felt	10329	Gear Case Adaptor Flange
10311	Screw M2.6 x 3 Rd. Hd.	10391	Spring	10331	Motor Shaft
10313	Gear Retainer	10407	Motor Assembly 110 volts	10333	Screw 10-32 x 1 Button Hd. Socket Cap (Switch Box)
10315	Gear only	10408	Carbon Brush, each	10334	Grip
10320	Worm Assembly	10409	Motor Assembly 220 volts	10336	Motor Shaft Housing Assembly
10324	Rollpin 2 x 10	10410	Motor Case	10352	Screw 10-32 x 3/16 Socket Set, Cone Pnt. (Flanges)
10325	Retaining Ring	10411	Switch Lever	10361	Switch Box
10339	Cutting Guide Assembly	10414	Holder only	10362	Switch Box Bracket
10340	Cutting Guide w/Blade	10415	Clip	10407A	Motor Assembly 110 Volts
10341	Counter-Cutting Blade	10416	Switch	10409A	Motor Assembly 220 Volts
10345	Baseplate	10418	Brush Cap	10428A	Coupling
10346	Screw M2.6 x 3 Pan Hd.	10419	Sheath	10717A	Switch
10347	Screw M 3 x 6 Pan Hd.	10420	Screw 4 x 5/16 Pan Hd.	B24T	Screw 6-32 x 3/8 Socket Hd. Cap (Switch Box Bracket)
10348	Cutting Guide only	10423	Screw M3 x 8 Flat Hd.		
10349	Clamp (not shown)	10425	Spring		
10370	Sharpener Assembly	10426	Screw M3 x 4 Fil. Hd.		
		10428	Shaft Coupling		
		10433	Knives Lock Screw		